

RFQ 2FY20 Vendor Question 14

1. In the Kennel building it's calling for $\frac{3}{4}$ " plywood and $\frac{5}{8}$ " drywall on the bottom of the trusses with R-30 batt insulation.
 - a) Is the plywood Fire Rated or PT? *The $\frac{3}{4}$ " plywood would P.T.*
 - b) Also does this occur over the office area? I would assume that the plywood and insulation does but the drywall is as shown. *This is correct.*